


# Lecture #17

**Prof. John W. Sutherland**


**Oct. 5, 2005**

# 8 Rules for Chart Interpretation


- Test 1: Extreme points
- Test 2: 2 out of 3 points in zone A or beyond
- Test 3: 4 out of 5 points in zone B or beyond
- Test 4: Runs above / below the centerline
- Test 5: Linear trend
- Test 6: Oscillatory trend
- Test 7: Avoidance of zone C
- Test 8: Run in zone C



**Figure 6.2** Appearance of a Process in Good Statistical Control




**Figure 6.3** Control Chart Zones to Aid Chart Interpretation




**Remember: No zones on the R chart**

# Test 1 examples - Extreme Points



## Test 2: 2 out of 3 Points in Zone A or Beyond



## Basis for Test 2


Prob (A Point in Zone A or Beyond) = .0227

Prob (Two Points in a Row in Zone A or Beyond)  
=  $(0.0227) * (0.0227) = 0.00052$


Very small relative to  $\alpha/2 = 0.00135$   
-- 2 points in a row in zone A is too restrictive

What about 2 out 3 in zone A or beyond? Two ways  
for this to occur: (A -- not A -- A) OR (not A -- A -- A)  
=  $2 * (0.0227)^2 * (0.9773) = 0.0010$  -- close to  $\alpha/2$


# Test 2 examples - 2 out of 3 Points in Zone A or Beyond




# Additional Comments on Test 2



# Test 3 examples - 4 out of 5 Points in Zone B or Beyond



## Test 4 examples - Runs Above or Below the Centerline




Probability Above / Below CL = 0.5


Prob (8 in a row above) =  $(0.5)^8 = 0.0039$

FYI...  $(0.5)^9 = 0.00195$        $(0.5)^{10} = 0.000977$


## Test 5 examples - Linear (Upward / Downward) Trend



## Test 6 examples - Oscillatory Trend




## Test 7 examples - Avoiding Zone C



Prob (one point outside zone C) =  $1 - 0.68 = 0.32$


$(0.32)^8 = 0.00011$  -- very small

## Test 8 examples - Run in Zone C




Prob (being in zone C) = 0.68

Prob (15 in a row in zone C) =  $(0.68)^{15} = 0.0031$



## Example - Simultaneous Application of More Than One Test for Out-of-Control Conditions



**Figure 6.16** Classical Control System View of SPC Implementation







Figure 6.17 General Structure for a Scatter Diagram



**Figure 6.18** Examples of No Correlation (a) and Positive Correlation (b)



**Figure 6.19** Scatter Diagram for Surface Roughness Versus Tool Condition




Figure 6.20 Pareto Diagram of Molding Defects




Figure 6.21 Pareto Diagram of Defects Occurring in an Accounts Payable Department




Figure 6.22 Structure of the Cause-and-Effect Diagram




Figure 6.23 Fully Developed Cause-and-Effect Diagram for the Black-Spot Symptom