


Lecture # 26

Vishesh Kumar

Oct. 26, 2005


Assembly Tolerances



We might naively set the assembly tolerance by simply adding tolerances: ± 0.017

Concerned that parts 1, 2, & 3 might be selected right at the tolerances - want assembly to be ok

Individuals & Assemblies




Let's assume specs are $\pm 4\sigma$ from the mean/nominal

Probability of a point at or below $-4\sigma = 0.00003$

Probability of simultaneously obtaining 3 such points: $(0.00003)^3 = 2.7 \text{ E-}14$ (1 in 37 trillion!!)

Describing the Assembly




$$X_A = X_1 + X_2 + X_3$$

$$\mu_A = \mu_1 + \mu_2 + \mu_3 = 3.75$$

$$\sigma_A^2 = \sigma_1^2 + \sigma_2^2 + \sigma_3^2 = 8.0625 \times 10^{-6} \quad \sigma_A = 0.00284$$

Assembly Distribution



If we again assume that the specs are $\pm 4\sigma_A$ from the mean/nominal, then the tolerance is ± 0.01136


This differs significantly from that obtained by adding!!!

Forces at Work

- Random assembly
 - Statistical (so far normal) distribution of part dimensions
 - Additive Law of Variances
-

- In our example we also assumed that the process was centered at the nominal value.
- Tolerances at $\pm 4\sigma$

Assembly Example



How do we obtain the tolerances on the individual parts? Divide 0.009 by 3 = 0.003 ??

Let's use the relations that we have developed to obtain the unknown tolerance. Assume 1=2=3

Remember that $X_A = X_1 + X_2 + X_3$


Mean of individual distributions at 0.30

Assembly has tolerance of ± 0.009


If tolerances are at $\pm 4\sigma_A$, then $\sigma_A = ??$

Since $\sigma_A = \sqrt{\sigma_1^2 + \sigma_2^2 + \sigma_3^2} = \sqrt{3\sigma_p^2}$, $\sigma_p = ??$

If we again put the specs for the individual parts at $\pm 4\sigma_p$, this turns out to be ± 0.0052



Effect of Process Centering




Assembly: 0.390 ± 0.050 inch (0.34 -- 0.44)

If tolerances are at $\pm 3\sigma_A$, $\sigma_A = 0.017$

$$\text{Since } \sigma_A = \sqrt{\sigma_1^2 + \sigma_2^2 + \sigma_3^2} = \sqrt{3\sigma_p^2}, \quad \sigma_p = 0.010$$


So, for individ. parts: 0.130 ± 0.030 inch

What if we reduce σ_p from 0.010 to 0.005??




$\mu_A =$

$\sigma_A =$




What if we shift process mean to 0.115??




$\mu_A =$

$\sigma_A =$



Another Example




Three identical parts

Manufacturing process -- $C_p = 1.5$ (at least)

What will the individual process σ_x be, if tolerances are obtained by simple division?

**Find (i) standard deviation for the processes
(ii) tolerances for individual parts**

Another Example



For now, let's assume hole & pin producing processes are centered at the nominal values and that processes have Cp values of 1.0.


What does clearance dist. look like??

Clearance Distribution

$$C = H - P$$


$$\mu_C = \mu_H - \mu_P = 0.035$$

$$\sigma_C^2 = \sigma_H^2 + \sigma_P^2 \quad \text{----} \quad \sigma_C = 0.007$$




What can go Wrong?


- We have already seen that if our individual processes (in this case pin and hole) do not remain centered - the results can be disastrous.
- What if our processes are not maintained in a state of statistical control?



Histogram - Hole Dimension



Histogram - Pin Dimension



Histogram - Clearance Dimension

