How Al is changing the safety landscape from reactive to preventive

ANDREA SCHMIDT Dir. Solution Architecture SparkCognition May 2023

How AI is changing the safety landscape

What you will learn

- 1. How to identify opportunities for AI in safety
- 2. How to use video data for a proactive safety program
- 3. Industry examples of AI in safety
- 4. Challenges in adoption


 $\frac{4}{7}$

Why has improvement stagnated?

10 years of flat-lined numbers


Injury Incident Rate

Estimated rate of self-reported workplace non-fatal injuries per 100,000 workers




Identifying opportunities for AI in Safety

Using AI to do more with less.



Al for Proactive Information Capture

Visual AI for Real Time Insights Delivery




AI Enabled Workflows

Visual AI for Real Time Insights Delivery

24/7 DATA CAPTURE







 $\frac{4}{7}$

LLMs and Generative Al

Visual AI for Real Time Insights Delivery

ilure Report #1	CUSTOMER / WELL INFORMATION:	Sparkbot	1010 0010 1001 0011 1110 0110
ilure Report #2	Customer Name: CALLON Install Date: 3/6/2017 Well Name: CHEEK 28-21 #95H Pull Date: 6/6/2017 Report #: 2017216 Installed/Run Days: 92 Report Completed by: Ade/Shelbi Dismantle Date: 6/16/2017 Reason for Pull: Low Production Report E: 6/21/2017 To: Michael Hosick CC: Duane Bullock	There is sand in the tailpipe joint. What could be the cause?	0110 0111 0001 1010 0011 1101 0011 1110 0110 0110 0111 0001 1010 0011 1101 0010 1001 0001
ilure Report #3	ID: Michael Hostik U: Duale bulkek Customer Witness: No Witness Name: NA NOTES Ten joints of tailpipe full of sand. Bottom of desander contains a hole. Up and down thrust washers missing on impeller. Diffuser bore contains excessive radial wear. Most of the diffusers had small holes or erosional wear along the balance ring bores. UT seal had a large amounts of sand and water throughout the chambers. Bags filled with watery oil. UT motor had watery oil. CT motor base end and sensor had water. Motors were not grounded. CL: Duale bulket COUSE OF FALURE CLSSIFICATION: H According to pull report, all ten joints of tailpipe were full of sand. Impeller balance rings and Diffuser balance ring bores showed severe scoring from abrasive/sand. Holes found on the balance ring and Diffuser balance ring bore. Stages also showed lots of radial wear on the diffuser bore. Seals failed due to the water and sand throughout the chambers. Seals failed due to the water and sand throughout the chambers. Motors were not grounded however did not pass hi-pot due to water contamination from the failed seals. Low production is due to holes found in the diffuser and stages radial wear. Mode of failure due to reservoir- sand. Samples collected are available for pickup here at the Odessa yard. RECOMMENDATIONS	 Based on the recommendations mentioned in the reports, the possible recommendations for addressing the issue are: 1. Clean out the well: This recommendation is mentioned in both reports as a possible solution to address the presence of sand or foreign matter in the equipment. 2. Perform hydrostatic testing on tubing: In one report, it is recommended to perform hydrostatic testing on the tubing to identify any potential holes or damages that could allow sand. Type a message 	
	- Clean Out Well	Actions (Coming Soon)	


- ✓ Generate Safety Reports for pre-work Safety Briefings
- ✓ Query Records and Summarize Findings

 $\frac{4}{V}$

SOP Compliance & Auditing

Visual AI for Real Time Insights Delivery

- ✓ 40% improvement in fire prevention SOPs
- ✓ 80% improvement in overall SOP adherence
- ✓ 250K annual cost reduction in audit documentation




 $\frac{1}{\sqrt{2}}$

Vehicle Near Miss

Visual AI for Real Time Insights Delivery

- ✓ Discovery of behaviors
- ✓ Implementation of new policy
- ✓ Quantified reduction of near-miss incidents






 $\frac{1}{\sqrt{2}}$

Machine Guarding & Utilization Tacking

Multi-purpose Applied Al




Material Handling Safety & SOP Compliance Multi-purpose Applied AI



Dock Door Safety & Productivity

Multi-purpose Applied Al



 $\frac{4}{7}$

How does Scene Understanding in Visual AI work?



 $\frac{1}{V}$

AI Technology Adoption Challenges

Multi-stakeholder Initiative

- 1. Integrations
- 2. Daily Users & Alert Chain of Responsibility
- 3. Network Security
- 4. Privacy & PII
- 5. Hardware Requirements
- 6. Success Criteria and Enterprise Value

Thank You

Let's talk about your AI for Safety

aschmidt@sparkcognition.com

Director, Solution Architecture at SparkCognition