

NFPA 660 & A Dust Hazard Analysis Case Study

Katie Kuhn

Process Safety Engineer
Fauske and Associates


NFPA 652 → NFPA 660

- NFPA 660 has been effective since December 6th, 2024
- Consolidated and replaced NFPA 652 and the commodity standards
- NFPA 660 did not consolidate NFPA 68, 69, or any other supporting standards



The New – NFPA 660


- NFPA 652 chapters 1–9 → NFPA 660 chapters 1–10
- None → NFPA 660 chapters 11–20
- Commodity Standards → NFPA 660 chapters 21–25




Chapter 21 – Agricultural and Food




Chapter 23 – Sulfur



Chapter 25 – Combustible Dusts Not Otherwise Specified




Chapter 22 – Combustible Metals



Chapter 24 – Wood Processing and Woodworking

Compliance and Implementation

- International fire code ('27), International Building Code ('27), state fire codes, and municipal fire codes
- Insurance carriers
- OSHA General Duty Clause
 - “shall furnish to each of his employees employment and a place of employment which are free from **recognized hazards** that are causing or are likely to cause **death** or **serious physical harm** to his employees”



Wood Pellet Explosion Case Study

- Facility overview
- Incident Description
- Incident Investigation
 - Material Characteristics
 - Safeguards
 - Shortfalls
- How the incident was addressed




Facility Background


- Wood pellet manufacturing facility
- Indoor/outdoor
- Producing / receiving
 - Kiln dried particulate
 - Green wood particulate
- Producing
 - Final products
 - Dried wood pellets
 - Wood products
 - Intermediate materials
 - Green wood chips + milled
 - Kiln dried wood + milled



Manufacturing Process – High Level




Facility Overview – Block Flow




20130819-4AT
Proprietary Property of
Fauske & Associates, LLC


The Incident – Facility Map




20130819-8AT
Proprietary Property of
Fauske & Associates, LLC



The Incident – Facility Photos





Material Testing



Sample Identification	Sample Point #	Moisture content	Particle Screening Result (µm)
Green Storage Pile	1	> 50%	
Green After 1st Size Reduction	2	> 48%	
Green After Drying	3	10.4% - 14%	89% > 425
Green After 2nd Size Reduction	4	9.4% - 13.4%	77% > 425
Green After 3 rd Fuel Size Reduction	5	1.3% - 3.1%	70% > 425
Kiln Dried After 1 st Size Reduction	6	2.6	95% < 75
Both After Mixing	7	2.6	97% < 75


Safeguards In Place

- Explosion vent panel on pellet cooler bag house
 - Short (6 ft) ducting to the exterior of the building
- Isolation valve between pellet cooler bag house and cooler
- Effective housekeeping in Hammer Mill Building
 - No exposed combustibles



Shortfalls

- Protection Failures
 - Inaccurately sized explosion vents
 - OSHA data vs Test data
 - Destruction of doors
 - Lack of reinforced ductwork
 - Inappropriately directed explosion vents
 - Lack of explosion venting on silos
- Lack of Combustible Dust Management Programs
 - No written management of change (MoC) program
 - No written housekeeping program
 - No written preventative maintenance (PM) program
- Insufficient electrical Area Classification



Continuation of the Case

- Fauske and Client evaluated prescriptive options
- Subsequent PHA
- Performance Based Design Option
 - Chapter 6



Thank you!

Katie Kuhn

Kuhn@fauske.com

DHA@fauske.com

Dust@fauske.com