

ECE 477 Digital Systems Senior Design Project

Module 9

Board Assembly and Soldering Techniques

Outline

- “I’ve got my board, now what?”
- “Which end of this thing gets hot?”
- “Flux is your friend.”
- “Static is your enemy.”
- “Do unto your iron, as you would have it do unto you.”
- “Everything is awesome, everything is cool when we’re part of a team.”

“I’ve got my board, now what?” - 1

- Visually inspect board against printout of top/bottom copper
 - Confirm footprint and drill size of all parts
 - Minimum trace: 0.0049”
 - Minimum space: 0.0045”
 - Minimum finished hole size: 0.010”
 - If necessary, use drill press in lab to drill out any holes that need to be enlarged (e.g., headers)
 - Problem: your vias will already be plated!
 - Look for shorted traces and traces that got etched away (will be limited need to do this)
 - Using a sharp hobby knife, carefully scrape away copper that did not get etched between traces
 - “Fly wire” any traces that got etched away
 - If “major” problems – contact fab house for replacement

"I've got my board, now what?" - 2

- "Ohm out" traces, especially those with vias
 - probably not essential if you used traces > 8mil
- Install power supply components (diodes, voltage regulators, filter capacitors, etc.)
 - **never ever attempt to solder a "live circuit"**
 - test and "burn in" your power supply
 - measure all supply voltages and look at them on an oscilloscope to determine how "quiet" they are
 - make sure correct supply voltage appears at correct pins of each IC and that, *under load* (a resistor), are within tolerance
 - note that some SMPS circuits will not function without a load – use an appropriately sized resistor

“I’ve got my board, now what?” - 3

- Install all bulk and bypass capacitors and test all supply rails *again* to make sure nothing got “shorted” in the process
- Install microcontroller, reset circuit, crystal (or oscillator) circuit, flash programming header, and any other test points/headers
 - power up the board and “smoke test”
(hint: if the microcontroller starts to get warm real fast, something is wrong!)
 - load a simple “heartbeat” program that toggles a port pin – verify basic functionality

“I’ve got my board, now what?” - 4

- Install RS232 level translator chip (where applicable) and associated components (9-pin D connector, capacitors, etc.)
 - power up and “smoke test”
 - load a simple program that “echoes” data to/from a virtual terminal – verify basic functionality “HELLO WORLD”
- Add each interface circuit to your board block-by-block and “smoke test” each one as well as test/verify functionality

“I’ve got my board, now what?” - 5

It is very important that each interface circuit be constructed and tested block-by-block!

Don’t add “new” circuitry until all the “existing” circuitry is fully functional!!

NOTE: If you need to “fly wire” any signal traces, use 30 gauge “wire-wrap” wire (use thicker wire, e.g., solid 24 gauge, for power and ground connections)

“Which end of this thing gets hot?” - 1

- Heat transfer: solder will flow from the colder region to the warmer region if it can
- Secret
 - choose the right iron tip (and temperature) so the warm region will be effective
 - position the iron correctly so the solder flows in a path that makes sense
 - provide an environment for the solder to flow – need *flux* and clean, smooth metal surface
 - never **ever** attempt to solder a “live circuit”


“Which end of this thing gets hot?” - 2

■ Tip selection

- different types: point, blade, chisel
- bottom line: want to “match” geometry of surface area warmed by tip with geometry of surface area to be soldered
 - conical (point) tip → circular area
 - screwdriver (blade) tip → rectangular area
 - chisel tip → triangular region
- if the tip is *too small*, it is difficult to get enough heat transfer for the solder to flow
- if the tip is *too large*, the flow of solder cannot be contained in a small area


Name That Tip

Chisel Soldering Tip .125" 700°F, Alternate for Weller PTC7



chisel (bevel)

LT Series Bent Chisel Soldering Tip .032 x .063" for WSP80 Iron



bent chisel

Screwdriver Soldering Tip .031" 600°F, Alternate for Weller PTH6



screwdriver
(blade)

Conical Soldering Tip .031" 700°F, Alternate for Weller PTP7



conical (point)

“Which end of this thing gets hot?” - 3


- Tip selection

- note that **chisel (bevel)** and **screwdriver** tips can be very useful for:
 - soldering groups of pins “at once” on surface-mount devices
 - removing “solder bridges” among several pins at once

- Basic soldering technique

- if needed, apply flux with pen/brush (e.g., for fine-pitch surface-mount components)
- heat area with iron tip (2-3 seconds)
- apply solder and allow to flow
- remove heat and allow to cool


Using the Right Amount of Solder



a) Minimal b) Optimal c) Excessive


see http://www.elexp.com/t_solder.htm

What's Wrong With These Pictures?



see http://www.elexp.com/t_solder.htm


What's Wrong With These Pictures?



Bad soldering of
terminal wire

see http://www.elexp.com/t_solder.htm

What's Wrong With These Pictures?




Bad soldering of
terminal wire

Bad soldering of
PCB pad

see http://www.elexp.com/t_solder.htm

What's Wrong With These Pictures?



Bad soldering of
terminal wire

Bad soldering of
PCB pad

Bad soldering of
both (solder did
not flow properly)

see http://www.elexp.com/t_solder.htm

“Which end of this thing gets hot?” - 4

- Solder removal (de-soldering)
 - apply flux (if necessary)
 - heat area to be de-soldered (surface-mount parts require a special heat gun to do this)
 - use solder wick (copper braid) or “solder sucker” to remove solder
- Cautions
 - “cold” solder joints (solder did not flow)
 - too much heat (components will be damaged and/or traces will peel off board)
 - access (be careful about assembly order!)
 - examine solder joints of surface mount components using microscope

“Flux is your friend.”


- Flux is a liquid in which solder can flow
- Most “electronic” solder contains some flux
- Without flux, solder will be pasty and sticky (refuse to flow)
- *The secret to soldering is using flux to make solder flow, and then controlling the heat so it flows under control*

“Static is your enemy.”


- Many of the parts you will be using are *static sensitive* (can be damaged by ESD)
- *To avoid damaging your components, do all of your board construction on the anti-static (gray or blue) mats in lab*
- *When soldering, use an anti-static wrist band and make sure it is connected to ground*

“Do unto your iron, as you would have it do unto you.”


- Wet the sponge with **distilled water** *before* you begin
- Choose the iron with the appropriate tip for the job and set the temperature accordingly (bent chisel is a good place to start)
- Tin and clean the tip *before* starting
- Clean the tip *frequently* during use
- Tin the tip when you are finished and **TURN OFF** the iron
- Use soldering irons only for soldering!




conical (point) tip



screwdriver (blade) tip





“Everything is awesome, everything is cool when we’re part of a team.”

- Professional SMT Soldering Demo
- Fine Pitch Drag Soldering
- Leaded vs. Lead-Free Solder
- Circuit Board Manufacturing
- SMD Removal Using a Chip Quik Kit
- Everything is Awesome!