

---

# **Lecture Set 6: Permanent Magnet AC Machines**

S.D. Sudhoff

Spring 2021

# About this Lecture Set

---

- Reading
  - *Electromechanical Motion Devices, 2<sup>nd</sup> Edition,*  
Chapter 8
- Goal
  - Understand the theory and operation of the permanent magnet ac machine


---

# *Lecture 55*

## Topology

# A Brushless DC Machine


---



# Sample Applications


---

- Low Power:
  - Disk drive motors
- Medium Power:
  - Robot manipulators
  - Servo systems
  - Hybrid/electric vehicles
- High Power:
  - Ship and submarine propulsion
  - Wind turbines



# Disk Drive Motor


---





# 4 Hp BDC Machine

---








# Permanent Magnet Synchronous Machines

---

- **Radial Versus Axial**
- **Surface Mounted Versus Buried Magnet**
- **Sinusoidal Versus Non-Sinusoidal**

# Radial Surface Mounted PMSM

---




---

## *Lecture 56*

# Machine Variable Model Voltage and Flux Linkages

# 3-Phase PMSM



# 3-Phase PMSM

---

- Notation

$$(\mathbf{f}_{abc})^T = [f_{as} \quad f_{bs} \quad f_{cs}]$$

- Voltage equations

$$v_{as} = r_s i_{as} + \frac{d\lambda_{as}}{dt}$$

$$v_{bs} = r_s i_{bs} + \frac{d\lambda_{bs}}{dt}$$

$$v_{cs} = r_s i_{cs} + \frac{d\lambda_{cs}}{dt}$$

$$\mathbf{v}_{abc} = r_s \mathbf{i}_{abc} + p \boldsymbol{\lambda}_{abc}$$

# 3-Phase PMSM

---

- Flux Linkage Equations

$$\boldsymbol{\lambda}_{abc s} = \mathbf{L}_s \mathbf{i}_{abc s} + \boldsymbol{\lambda}'_m$$

- where


$$\boldsymbol{\lambda}'_m = \begin{bmatrix} \lambda_{asm} \\ \lambda_{bsm} \\ \lambda_{csm} \end{bmatrix} = \lambda'_m \begin{bmatrix} \sin \theta_r \\ \sin(\theta_r - \frac{2}{3}\pi) \\ \sin(\theta_r + \frac{2}{3}\pi) \end{bmatrix}$$

$$\mathbf{L}_s = \begin{bmatrix} L_{ls} + L_{ms} & -\frac{1}{2}L_{ms} & -\frac{1}{2}L_{ms} \\ -\frac{1}{2}L_{ms} & L_{ls} + L_{ms} & -\frac{1}{2}L_{ms} \\ -\frac{1}{2}L_{ms} & -\frac{1}{2}L_{ms} & L_{ls} + L_{ms} \end{bmatrix}$$




# PM Terms – Intuitive Approach

---




# PM Terms – Intuitive Approach

---



# PM Terms – Intuitive Approach

---



# Inductances

---

- We will assume the following

$$n_{as} = N_s \sin(P \phi_{sm} / 2)$$

$$n_{bs} = N_s \sin(P \phi_{sm} / 2 - 2\pi/3)$$

$$n_{cs} = N_s \sin(P \phi_{sm} / 2 + 2\pi/3)$$

- It follows that

$$w_{as} = \frac{2N_s}{P} \cos(P \phi_{sm} / 2)$$

$$w_{bs} = \frac{2N_s}{P} \cos(P \phi_{sm} / 2 - 2\pi/3)$$

$$w_{cs} = \frac{2N_s}{P} \cos(P \phi_{sm} / 2 + 2\pi/3)$$

# Inductances

---

- Recall

$$\frac{\lambda_{\alpha,m}}{i_{\beta}} = L_{m,\alpha\beta} = \mu_0 r L \int_0^{2\pi} \frac{w_{\alpha}(\phi) w_{\beta}(\phi)}{g(\phi)} d\phi$$

- From which we obtain

$$L_{asas} = \frac{4\pi\mu_0 r L N_s^2}{P^2 g} = L_{ms}$$

Doesn't include  
leakage

$$L_{asbs} = -\frac{2\pi\mu_0 r L N_s^2}{P^2 g} = -\frac{1}{2} L_{ms}$$

---


## *Lecture 57*

### Detailed Treatment of PMs



# PM Terms – Analytical Approach

---



# PM Terms – Def. of Elec. Quantities

---

$$\theta_r = P \theta_{rm} / 2$$

$$\omega_r = P \omega_{rm} / 2$$

$$\phi_s = P \phi_{sm} / 2$$

$$\phi_r = P \phi_{rm} / 2$$

# PM Terms

---

- Suppose the B field due to the PM may be expressed

$$B|_{\text{due to PM}} = \begin{cases} -B_{pm} & 0 \leq \phi_r \leq \pi \\ B_{pm} & \pi \leq \phi_r \leq 2\pi \end{cases}$$

and suppose

$$w_{as} = \frac{2N_s}{P} \cos(P\phi_{sm} / 2) = \frac{2N_s}{P} \cos(\phi_s)$$

# PM Terms

---

- It can be shown that

$$\lambda_{as} \Big|_{\text{due to PM}} = \lambda_m \sin \theta_r$$

where

$$\lambda_m = \frac{8rLB_{pm}N_s}{P}$$

# PM Terms

---

# PM Terms

---



# PM Terms

---

# PM Terms

---

# PM Terms

---

- Comment: The sinusoidal turns distribution gives rise to a sinusoidal flux linkage versus electrical rotor position characteristic

---

# *Lecture 57*

## Torque

# Expression for Torque

---

- It can be shown that

$$T_e = \frac{P}{2} \lambda_m [i_{as} \cos(\theta_r) + i_{bs} \cos(\theta_r - 2\pi/3) + i_{cs} \cos(\theta_r + 2\pi/3)]$$

# Expression for Torque

---



# Expression for Torque

---

# Expression for Torque

---

# Expression for Torque

---

# Expression for Torque

---

---

## *Lecture 58*

# Reference Frame Analysis

# Machine Equations in Rotor Ref. Frame

---

- Consider the transformation

$$\mathbf{f}_{qd0s}^r = \mathbf{K}_s^r \mathbf{f}_{abcs}$$

- Where

$$(\mathbf{f}_{qd0s}^r)^T = [f_{qs}^r \quad f_{ds}^r \quad f_{0s}]$$

$$\mathbf{K}_s^r = \frac{2}{3} \begin{bmatrix} \cos \theta_r & \cos(\theta_r - \frac{2}{3}\pi) & \cos(\theta_r + \frac{2}{3}\pi) \\ \sin \theta_r & \sin(\theta_r - \frac{2}{3}\pi) & \sin(\theta_r + \frac{2}{3}\pi) \\ \frac{1}{2} & \frac{1}{2} & \frac{1}{2} \end{bmatrix}$$

# Machine Equations in Rotor Ref. Frame

---

# Machine Equations in Rotor Ref. Frame

---

- Voltage

$$v_{qs}^r = r_s i_{qs}^r + \omega_r \lambda_{ds}^r + p \lambda_{qs}^r$$

$$v_{ds}^r = r_s i_{ds}^r - \omega_r \lambda_{qs}^r + p \lambda_{ds}^r$$

- Flux Linkage

$$\lambda_{qs}^r = L_{ss} i_{qs}^r$$

$$\lambda_{ds}^r = L_{ss} i_{ds}^r + \lambda'_m$$

- Torque

$$T_e = \frac{3}{2} \frac{P}{2} \lambda'_m i_{qs}^r$$



# Aside: Some Shorthand

---

$$c = \cos(\theta_r)$$

$$c^- = \cos(\theta_r - 2\pi / 3)$$

$$c^+ = \cos(\theta_r + 2\pi / 3)$$

$$s = \sin(\theta_r)$$

$$s^- = \sin(\theta_r - 2\pi / 3)$$

$$s^+ = \sin(\theta_r + 2\pi / 3)$$

# Aside: Some Trig IDs

---

$$\cos(x) + \cos(x - 2\pi/3) + \cos(x + 2\pi/3) = 0$$

$$\sin(x) + \sin(x - 2\pi/3) + \sin(x + 2\pi/3) = 0$$

$$\cos(x)\cos(y) + \cos(x - 2\pi/3)\cos(y - 2\pi/3) + \cos(x + 2\pi/3)\cos(y + 2\pi/3) = \frac{3}{2}\cos(x - y)$$

$$\sin(x)\sin(y) + \sin(x - 2\pi/3)\sin(y - 2\pi/3) + \sin(x + 2\pi/3)\sin(y + 2\pi/3) = \frac{3}{2}\cos(x - y)$$

$$\sin(x)\cos(y) + \sin(x - 2\pi/3)\cos(y - 2\pi/3) + \sin(x + 2\pi/3)\cos(y + 2\pi/3) = \frac{3}{2}\sin(x - y)$$

---

## *Lecture 59*

# Transformation of Voltage Equations

# Transformation of Voltage Equations

---

# Transformation of Voltage Equations

---

# Transformation of Voltage Equations

---

# Transformation of Voltage Equations

---

# Transformation of Voltage Equations

---



# Transformation of Voltage Equations

---

- This yields

$$\mathbf{v}_{qd0s}^r = \mathbf{r}_s \mathbf{i}_{qd0s}^r + \omega_r \boldsymbol{\lambda}_{dqs}^r + p \boldsymbol{\lambda}_{qd0s}^r$$

- Where

$$(\boldsymbol{\lambda}_{dqs}^r)^T = [\lambda_{ds}^r \quad -\lambda_{qs}^r \quad 0]$$

- In expanded form

$$v_{qs}^r = r_s i_{qs}^r + \omega_r \lambda_{ds}^r + p \lambda_{qs}^r$$

$$v_{ds}^r = r_s i_{ds}^r - \omega_r \lambda_{qs}^r + p \lambda_{ds}^r$$

$$v_{0s} = r_s i_{0s} + p \lambda_{0s}$$

---

## *Lecture 60*

# Transformation of Flux Linkage Equations

# Transformation of Flux-Linkage Equations

---

# Transformation of Flux-Linkage Equations

---

# Transformation of Flux-Linkage Equations

---

# Transformation of Flux-Linkage Equations

---

# Transformation of Flux-Linkage Equations

---

# Transformation of Flux-Linkage Equations

---



# Transformation of Flux-Linkage Equations

---

- This yields

$$\lambda_{qd0s}^r = \begin{bmatrix} L_{ls} + \frac{3}{2}L_{ms} & 0 & 0 \\ 0 & L_{ls} + \frac{3}{2}L_{ms} & 0 \\ 0 & 0 & L_{ls} \end{bmatrix} \begin{bmatrix} i_{qs}^r \\ i_{ds}^r \\ i_{0s} \end{bmatrix} + \lambda'_m \begin{bmatrix} 0 \\ 1 \\ 0 \end{bmatrix}$$

- Or in expanded form

$$\lambda_{qs}^r = L_{ss}i_{qs}^r \quad \lambda_{ds}^r = L_{ss}i_{ds}^r + \lambda'_m \quad \lambda_{0s} = L_{ls}i_{0s}$$

- Where

$$L_{ss} = L_{ls} + \frac{3}{2}L_{ms}$$

---

## *Lecture 61*

# Transformation of Torque Equation

# Transformation of Torque Equation

---

- Start with

$$T_e = \frac{P}{2} \lambda_m [i_{as} \cos(\theta_r) + i_{bs} \cos(\theta_r - 2\pi/3) + i_{cs} \cos(\theta_r + 2\pi/3)]$$

# Transformation of Torque Equation

---

- Finally, we arrive at

$$T_e = \frac{3}{2} \frac{P}{2} \lambda'_m i_{qs}^r$$

---

## *Lecture 62*

### Handy Stuff

# Zero Sequence

---

# Zero Sequence

---

# RMS and QD Components

---



# RMS and QD Components

---

# RMS and QD Components

---

# RMS and QD Components

---

---

## *Lecture 62*

# Voltage Source Operation

# Voltage Source Operation

---

- In this mode, idealized voltage applied is

$$v_{as} = \sqrt{2}v_s \cos \theta_{esv}$$

$$v_{bs} = \sqrt{2}v_s \cos\left(\theta_{esv} - \frac{2}{3}\pi\right)$$

$$v_{cs} = \sqrt{2}v_s \cos\left(\theta_{esv} + \frac{2}{3}\pi\right)$$

- Where

$$\theta_{esv} = \theta_r + \phi_v$$

# Applied Voltage in QD Variables

---

- We can show that

$$v_{qs}^r = \sqrt{2}v_s \cos \phi_v$$

$$v_{ds}^r = -\sqrt{2}v_s \sin \phi_v$$

# Applied Voltage in ABC Variables

---

# Applied Voltage in QD Variables

---



# Analysis of Steady State Operation

---

- Prediction of Q- and D-Axis Currents

# Analysis of Steady State Operation

---

# Analysis of Steady State Operation

---

# Analysis of Steady State Operation

---

# Example 1

---

- Consider a machine with the following parameters

$$r_s = 3.1 \Omega$$

$$P = 4$$

$$L_{ss} = 12.1 \text{ mH}$$

$$\lambda_m = 0.156 \text{ Vs}$$

$$N = 3$$

- Further suppose

$$V_s = 100$$

$$\phi_v = 0$$

$$\omega_{rm} = 1800 \text{ RPM}$$

- Find the torque and efficiency

# Example 1


---

## Example 2

---


- Consider the machine with parameters of example 1.
- Plot the torque speed and rms current speed curves

# Example 2





# Example 2



# Optimization of Phase Advance

---

# Optimization of Phase Advance

---

---

## *Lecture 63*

# Current Source Operation

# Current Source Operation

---

- Interpretation 1 (ABC Variable)

# Current Source Operation

---

- Interpretation 2 (Torque Transducer)

# Desired D-Axis Current

---

# Example 3

---

- Consider a machine with the following parameters

$$r_s = 3.1 \Omega$$

$$P = 4$$

$$L_{ss} = 12.1 \text{ mH}$$

$$\lambda_m = 0.156 \text{ Vs}$$

$$N = 3$$

- Plot the voltage required and efficiency for the following conditions

Torque command: 2 Nm, d-axis current 0 A

Torque command: 6 Nm, d-axis current 0 A


Torque command: 6 Nm, d-axis current -6 A



# Example 3


---

# Example 3



# Example 3

---



---

## *Lecture 63*

# Flux Weakening

# Effect of D-Axis Current on Voltage

---

# D-Axis Injection

---

# D-Axis Injection

---

# D-Axis Injection

---



# D-Axis Injection

---

# D-Axis Injection

---

## Example 4

---

- At 2000 rpm, the zero-to-peak line-to-line voltage has a 100 V amplitude and a frequency of 100 Hz. Compute  $\lambda_m$  and  $P$ .
- At standstill and at 60 Hz, the impedance looking into the a- to b-phase is  $0.2+2j$ . Find  $r_s$  and  $L_{ss}$ .

# Example 4 – Part 1

---

# Example 4 – Part 1

---

# Example 4 – Part 1

---

# Example 4 – Part 1

---

# Example 4 – Part 2

---



# Example 4 – Part 2

---

# Example 4 – Part 2

---