

CE 603 Photogrammetry II

Triangulation – passpoint selection

- You are assigned photos as follows
 - Boller: 5-9, 5-10; Carr: 5-11, 5-12; together: 5-13
 - Jo: 6-9, 6-10; Kim: 6-11, 6-12; together: 6-13
 - Liang: 7-9, 7-10; Su: 7-11, 7-12; together: 7-13
- Select 6 points on each of your photos (you may collaborate on cross-strip tie points)
- Document your selections with an overview, and a zoom-in view(s) for each points so that others may unambiguously identify them
- Make a nice document and email to me, then I publish everything on the web, together with control point descriptions.
- When you see all of the points that fall on your photo, then measure them (line,sample) (convention upper left = 0,0)


CE 603 Photogrammetry II

- File should be named: phof_n.dat where f=flight, n=number
- Contents of file should be ascii text, no formatting, beginning with 8 fiducial marks in order 1-8, (we are getting calibration report from the vendor) followed by pass points and control points in any order.
- Entries should be ID-line-sample, lower case, delimited by spaces, as shown

```
fid1      line      sample
fid2      line      sample
fidX      line      sample
p5_9_1    line      sample
p5_9_2    line      sample
gcp1      line      sample
gcp2      line      sample
p5_9_3    line      sample
```

Pho5_9.dat

CE 603 Photogrammetry II



Passpoint labeling convention for ce603 sub-block of the may04 nga/surdex photography. f=flight number (5,6,7), n=photo number

CE 603 Photogrammetry II

