

# Purdue Pilots Inc. Meeting Minutes

September 29, 2015

---

## **President**

N38394 flew with no issues after mall event.

Make sure the doors on the airplanes do not close on the seatbelt to prevent damage.

## **Treasurer's Report**

none

## **Maintenance Report**

N38394 did not reliably start due to battery issues. Battery replaced on September 24, 2015. Report any issues after the date.

GPS in N38394 has been updated.

## **Public Relations:**

Mall event was success.

Recommend laying out a step by step plan for the next event and pulling the plane out of the gate the night before.

Next meeting: Wed. October 21, 2015

6:45 PM

Room PHYS 338

General Meeting