

Efficiency of Operations
HMA Economics 101
North Central HMA Technical Conference
January 10, 2007

Dudley Bonte
Rieth-Riley Construction Co.

QUALITY CONTROL

ALWAYS

COSTS LESS THAN


“REMOVE & REPLACE”

**Dud's Top 10 Ways
to Manage Risk
(Efficiency)
through QC at a
HMA Facility**

10. Remember the Basics



9. Do Your Homework



8. Understand the Specifications

INDIANA

DEPARTMENT
OF
TRANSPORTATION

STANDARD
SPECIFICATIONS

*EFFECTIVE FOR LETTINGS
ON OR AFTER
SEPTEMBER 1, 2003*

Includes November 14, 2002 Minutes

1999

7. Minimize the Risks Before Production




6. Trial a New Mix Design Where the Risk is Low



5. Be Creative- Estimate Properties Early



4. When Trouble Shooting- Look for the Root Cause



3. Control What You Can Control



2. Provide the Proper Tools



1. Know When to Stop and Regroup

