Building on Faults: the 1999 Turkey Earthquake




by Antonio Bobet Purdue University March 31, 2006


Outline

- Overview
- Shaking Damage
- Fault Rupture
- Near Fault Effects
- Rigid vs. Flexible Structures
- Conclusions


— Overview —




Overview -




Overview —




Overview




Overview






— Overview —





- Overview ——





Overview —





- Overview ——









Adapazari Localized damage

Overview —



Overview —




Adapazari. Typical Foundation

- Overview ——



Overview —






- Overview ——



– Overview ——



- Overview ——



— Overview —


LOG OF TEST BORING Boring No.: © C-12/4357 Location: Dizee Town NE Date: 16/10/63		CIVIL ENGINEERING P. U.R. D. U.F. UNIVERSITY		LOG OF TEST BORING Boring No.: C-12/4337 Location: Dizee, NE Date: 16/10/63		linate 2	ENCINIERING PURDUF			LOG OF TEST BORING Boring No.: O C-12/4357 Location: Dizce.NE Date: 25/9/63 16/10/63		Coordinates x: y: z: Sheet 3 of			125.0m 3		
SAMPLE DESCRIPTION/CLASSIFICATION and REMARKS No. Y % Rec. % SPT		SAMPLE No. ^T Rec. SPT Depth ^P % SPT (m)		DESCRIPTION/CLASSIFICATION and REMARKS		DIL iu y	SAMPLE No. ^T y Rec. SPT Depth ^p % SPT (m)		Depth (m)	DESCRIPTION/CLASSIFICATION and REMARKS		SOIL PROF					
Sandy Chy. Sand, 10- Fire 4 Grave 30- Chy. Sand, 30- Sand, 30- Sand Sand, 30- Sand Sand, 30- Sand Sand, 30- Sand Sand, Sand Sand Sand Sand Sand Sand Sand Sand	ly clay. Gray. Datk gray with little gravel. Gray with gravel and sand gravel Dark gray. uy sand. Gray with little clay. with little sand. Gray of with little clay and sand of the gravel is peridotite and time.	GENERAL OB	110- 120- 130- 130- 140- 140- 140- 140- 140- 140- 140- 14	Clay Clayey sand Gravel Clay with sand			GENERAL		200 2 10 2 10 2 10 2 10 2 10 2 10 2 10	Sand with clay and silt Sandy clay Clay 259.50 End of Boring							
Aquifer (share d) 65-130m 8 hr +17.0m +10.5m 180-210m					,												

- Overview ——





Overview ——










Düzce

— Overview —

Overview ——



Bingöl






Outline


• Overview

- Shaking Damage
- Fault Rupture
- Near Fault Effects
- Rigid vs. Flexible Structures
- Conclusions

Shaking Damage —




Shaking Damage —



Outline

- Overview
- Shaking Damage
- Fault Rupture
- Near Fault Effects
- Rigid vs. Flexible Structures
- Conclusions





Fault Displacement





Tensile rupture









Compressive rupture




Fault gauge

Slickensides










Outline

- Overview
- Fault Rupture
- Shaking Damage
- Near Fault Effects
- Rigid vs. Flexible Structures
- Conclusions

- Near Fault Effects —


























Outline

- Overview
- Fault Rupture
- Shaking Damage
- Near Fault Effects
- Rigid vs. Flexible Structures
- Conclusions



Bolu Bridge






























Outline

- Overview
- Fault Rupture
- Shaking Damage
- Near Fault Effects
- Rigid vs. Flexible Structures
- Conclusions



- Geology is the critical factor
- Need site-specific analysis
- Construction details are critical
- Near-fault effects: elasto-plastic rebound

Acknowledgements -

SPONSORS

NSF

ACKNOWLEDGMENT

Mayor of Düzce Mayor of Bolu Mayor of Bingöl METU Turkish Waterworks USGS

COLLABORATORS

Ms. Lili Akin Mr. Jorge Casana Dr. Gabriel Fernández Ms. Yeliz Firat **Prof. Robert Frosch** Dr. Turel Gur Prof. Ayhan Irfanoglu Prof. Arvid Johnson Prof. Adolfo Matamoros Dr. Ali Cihan Pay Prof. Santiago Pujol Prof. Julio Ramírez Prof. Ken Ridgway Prof. Mete Sozen Mr. Tolga Yilmaz



"the team"