

RUNWAY OPS TIMES FOR HW9

- ◆ 45 sec. for landing aircraft to leave runway after touching down
- ◆ 5 sec. for departing aircraft to enter runway after previous aircraft clears runway
- ◆ 45 sec. for departing aircraft to “roll out and rotate”
- ◆ Consecutive landing aircraft must obey Table 11.14.
- ◆ Landing aircraft must be at least 2 n.mi. from runway when departing aircraft on runway begins rollout. T calc.+ 5 sec. (2nd item above)